

THEORY OF METAL MACHINING

- Overview of Machining Technology
- Theory of Chip Formation in Metal Machining
- Force Relationships and the Merchant Equation
- Power and Energy Relationships in Machining
- Cutting Temperature

Material Removal Processes

A family of shaping operations, the common feature of which is removal of material from a starting workpart so the remaining part has the desired shape

- Categories:
 - *Machining* – material removal by a sharp cutting tool, e.g., turning, milling, drilling
 - *Abrasive processes* – material removal by hard, abrasive particles, e.g., grinding
 - *Nontraditional processes* - various energy forms other than sharp cutting tool to remove material

Machining

Cutting action involves shear deformation of work material to form a chip

- As chip is removed, a new surface is exposed




Figure 21.2 - (a) A cross-sectional view of the machining process, (b) tool with negative rake angle; compare with positive rake angle in (a)

Why Machining is Important

- Variety of work materials can be machined
 - Most frequently applied to metals
- Variety of part shapes and special geometry features possible, such as:
 - Screw threads
 - Accurate round holes
 - Very straight edges and surfaces
- Good dimensional accuracy and surface finish

Disadvantages with Machining

- Wasteful of material
 - Chips generated in machining are wasted material, at least in the unit operation
- Time consuming
 - A machining operation generally takes more time to shape a given part than alternative shaping processes, such as casting, powder metallurgy, or forming

Machining in the Manufacturing Sequence

- Generally performed after other manufacturing processes, such as casting, forging, and bar drawing
 - Other processes create the general shape of the starting workpart
 - Machining provides the final shape, dimensions, finish, and special geometric details that other processes cannot create

Machining Operations

- Most important machining operations:
 - Turning
 - Drilling
 - Milling
- Other machining operations:
 - Shaping and planing
 - Broaching
 - Sawing

Turning

Single point cutting tool removes material from a rotating workpiece to form a cylindrical shape




Figure 21.3 (a) turning

Drilling

Used to create a round hole, usually by means of a rotating tool (drill bit) that has two cutting edges




Figure 21.3 - The three most common types of machining process: (b) drilling

Milling

Rotating multiple-cutting-edge tool is moved slowly relative to work to generate plane or straight surface

- Two forms: peripheral milling and face milling




Figure 21.3 - (c) peripheral milling, and (d) face milling

Cutting Tool Classification

1. *Single-Point Tools*

- One cutting edge
- *Turning* uses single point tools
- Point is usually rounded to form a *nose radius*

2. *Multiple Cutting Edge Tools*

- More than one cutting edge
- Motion relative to work usually achieved by rotating
- *Drilling* and *milling* use rotating multiple cutting edge tools.




Figure 21.4 - (a) A single-point tool showing rake face, flank, and tool point; and (b) a helical milling cutter, representative of tools with multiple cutting edges

Cutting Conditions in Machining

- The three dimensions of a machining process:
 - Cutting speed v – primary motion
 - Feed f – secondary motion
 - Depth of cut d – penetration of tool below original work surface

- For certain operations, material removal rate can be found as

$$MRR = v f d$$

where v = cutting speed; f = feed; d = depth of cut

Cutting Conditions for Turning




Figure 21.5 - Cutting speed, feed, and depth of cut for a turning operation

Roughing vs. Finishing in Machining

In production, several roughing cuts are usually taken on the part, followed by one or two finishing cuts

- *Roughing* - removes large amounts of material from the starting workpart
 - Creates shape close to desired geometry, but leaves some material for finish cutting
 - High feeds and depths, low speeds
- *Finishing* - completes part geometry
 - Achieves final dimensions, tolerances, and finish
 - Low feeds and depths, high cutting speeds

Machine Tools

A power-driven machine that performs a machining operation, including grinding

- Functions in machining:
 - Holds workpart
 - Positions tool relative to work
 - Provides power at speed, feed, and depth that have been set
- The term is also applied to machines that perform metal forming operations

Orthogonal Cutting Model

A simplified 2-D model of machining that describes the mechanics of machining fairly accurately




Figure 21.6 - Orthogonal cutting: (a) as a three-dimensional process

Chip Thickness Ratio

$$r = \frac{t_o}{t_c}$$

where $r = \text{chip thickness ratio}$; $t_o = \text{thickness of the chip prior to chip formation}$; and $t_c = \text{chip thickness after separation}$

- Chip thickness after cut is always greater than before, so chip ratio is always less than 1.0

Determining Shear Plane Angle

- Based on the geometric parameters of the orthogonal model, the shear plane angle ϕ can be determined as:

$$\tan \phi = \frac{r \cos \alpha}{1 - r \sin \alpha}$$

where r = chip ratio, and α = rake angle




Figure 21.7 - Shear strain during chip formation: (a) chip formation depicted as a series of parallel plates sliding relative to each other, (b) one of the plates isolated to show shear strain, and (c) shear strain triangle used to derive strain equation

Shear Strain

Shear strain in machining can be computed from the following equation, based on the preceding parallel plate model:

$$\gamma = \tan(\phi - \alpha) + \cot \phi$$

where γ = shear strain, ϕ = shear plane angle, and α = rake angle of cutting tool




Figure 21.8 - More realistic view of chip formation, showing shear zone rather than shear plane. Also shown is the secondary shear zone resulting from tool-chip friction


Four Basic Types of Chip in Machining

1. Discontinuous chip
2. Continuous chip
3. Continuous chip with Built-up Edge (BUE)
4. Serrated chip

Segmented Chip

- Brittle work materials (e.g., cast irons)
- Low cutting speeds
- Large feed and depth of cut
- High tool-chip friction

Figure 21.9 - Four types of chip formation in metal cutting:
(a) segmented




Continuous Chip

- Ductile work materials (e.g., low carbon steel)
- High cutting speeds
- Small feeds and depths
- Sharp cutting edge on the tool
- Low tool-chip friction

Figure 21.9 - Four types of chip formation in metal cutting:


(b) continuous



Continuous with BUE

- Ductile materials
- Low-to-medium cutting speeds
- Tool-chip friction causes portions of chip to adhere to rake face
- BUE formation is cyclical; it forms, then breaks off

Figure 21.9 - Four types of chip formation in metal cutting: (c) continuous with built-up edge



Serrated Chip

- Semicontinuous - saw-tooth appearance
- Cyclical chip formation of alternating high shear strain then low shear strain
- Most closely associated with difficult-to-machine metals at high cutting speeds





Figure 21.9 - Four types of chip formation in metal cutting: (d) serrated

Forces Acting on Chip

- Friction force F and Normal force to friction N
- Shear force F_s and Normal force to shear F_n

Figure 21.10 -
Forces in metal
cutting: (a) forces
acting on the chip
in orthogonal
cutting



Resultant Forces

- Vector addition of F and $N =$ resultant R
- Vector addition of F_s and $F_n =$ resultant R'
- Forces acting on the chip must be in balance:
 - R' must be equal in magnitude to R
 - R' must be opposite in direction to R
 - R' must be collinear with R

Coefficient of Friction

Coefficient of friction between tool and chip:

$$\mu = \frac{F}{N}$$

Friction angle related to coefficient of friction as follows:

$$\mu = \tan \beta$$

Shear Stress

Shear stress acting along the shear plane:

$$S = \frac{F_s}{A_s}$$

where A_s = area of the shear plane


$$A_s = \frac{t_o W}{\sin \phi}$$

Shear stress = shear strength of work material during cutting

Cutting Force and Thrust Force

- Forces F , N , F_s , and F_n cannot be directly measured
- Forces acting on the tool that can be measured:
 - Cutting force F_c and Thrust force F_t

Figure 21.10 - Forces in metal cutting: (b) forces acting on the tool that can be measured



Forces in Metal Cutting

- Equations can be derived to relate the forces that cannot be measured to the forces that can be measured:

$$F = F_c \sin\alpha + F_t \cos\alpha$$

$$N = F_c \cos\alpha - F_t \sin\alpha$$

$$F_s = F_c \cos\phi - F_t \sin\phi$$

$$F_n = F_c \sin\phi + F_t \cos\phi$$

- Based on these calculated force, shear stress and coefficient of friction can be determined

The Merchant Equation

- Of all the possible angles at which shear deformation could occur, the work material will select a shear plane angle ϕ which minimizes energy, given by

$$\phi = 45 + \frac{\alpha}{2} - \frac{\beta}{2}$$

- Derived by Eugene Merchant
- Based on orthogonal cutting, but validity extends to 3-D machining

What the Merchant Equation Tells Us

$$\phi = 45 + \frac{\alpha}{2} - \frac{\beta}{2}$$

- To increase shear plane angle
 - Increase the rake angle
 - Reduce the friction angle (or coefficient of friction)

- Higher shear plane angle means smaller shear plane which means lower shear force
- Result: lower cutting forces, power, temperature, all of which mean easier machining




Figure 21.12 - Effect of shear plane angle ϕ : (a) higher ϕ with a resulting lower shear plane area; (b) smaller ϕ with a corresponding larger shear plane area. Note that the rake angle is larger in (a), which tends to increase shear angle according to the Merchant equation

Power and Energy Relationships

- A machining operation requires power

The power to perform machining can be computed from:

$$P_c = F_c v$$

where P_c = cutting power; F_c = cutting force; and v = cutting speed

Power and Energy Relationships

In U.S. customary units, power is traditional expressed as horsepower (dividing ft-lb/min by 33,000)

$$HP_c = \frac{F_c v}{33,000}$$

where HP_c = cutting horsepower, hp

Power and Energy Relationships

Gross power to operate the machine tool P_g or HP_g is given by

$$P_g = \frac{P_c}{E} \quad \text{or} \quad HP_g = \frac{HP_c}{E}$$

where E = mechanical efficiency of machine tool

- Typical E for machine tools = ~ 90%

Unit Power in Machining

- Useful to convert power into power per unit volume rate of metal cut
- Called the *unit power*, P_u or *unit horsepower*, HP_u

$$P_u = \frac{P_c}{MRR} \quad \text{or} \quad HP_u = \frac{HP_c}{MRR}$$

where MRR = material removal rate

Specific Energy in Machining

Unit power is also known as the *specific energy* U

$$U = P_u = \frac{P_c}{MRR} = \frac{F_c v}{vt_o w} = \frac{F_c}{t_o w}$$

Units for specific energy are typically N-m/mm³ or J/mm³
(in-lb/in³)

Cutting Temperature

- Approximately 98% of the energy in machining is converted into heat
- This can cause temperatures to be very high at the tool-chip
- The remaining energy (about 2%) is retained as elastic energy in the chip

Cutting Temperature

- Several analytical methods to calculate cutting temperature
- Method by N. Cook derived from dimensional analysis using experimental data for various work materials

$$T = \frac{0.4U}{\rho C} \left(\frac{vt_o}{K} \right)^{0.333}$$

where T = temperature rise at tool-chip interface; U = specific energy; v = cutting speed; t_o = chip thickness before cut; ρC = volumetric specific heat of work material; K = thermal diffusivity of the work material

Cutting Temperature

- Experimental methods can be used to measure temperatures in machining
- Most frequently used technique is the *tool-chip thermocouple*
- Using this method, K. Trigger determined the speed-temperature relationship to be of the form:

$$T = K v^m$$

where T = measured tool-chip interface temperature